




XP-2000

XP-2000 FEATURES

- Windows Based Program
- 400 Amperes Capacity
- Arc Voltage Control
- Multiple Level Programming
- Weld Process Development
- Wire Feed
- Arc Oscillation
- Dual Gas Control with Sensors
- TIG/PLASMA



Inspection Type	WPM Correction Factor	Unit Name	Unit	Unit
001	0	Current Test	ins	ins
002	0	Wire Test	ins	ins
003	0	Travel Test	ins	ins
004	0	Wire Test	ins	ins
005	0	Visual Inspection	Check for porosity	Check for porosity
006	0	Visual Inspection	Check for cracks	Check for cracks
007	0	Visual Inspection	Check for spatter	Check for spatter
008	0	Visual Inspection	Check start & finish of weld	Check start & finish of weld